


Assembling Instruction For W14


Hardware




A*4




B*12




C*2




D*4



E*2




F*2




G*1


Components




① 1pc




② 1pc




③ 2pcs




④ 1pc




⑤ 1pc




⑦ 1pc




⑥ 1pc



⑧ 1pc



⑨ 2pcs



⑩ 2pcs

Assembling Instruction For W14

